

Inspection instructions

EDELRID HMS Bulletproof Triple / Triple FG

Issued by EDELRID, GmbH & Co. Isny, Germany 07/17/2018. The precautionary call for a safety check concerns both carabiner models with manufacturing codes 2018 01 and 2018 02:



HMS Bulletproof Triple
73727



HMS Bulletproof Triple FG
73728



Jul² Belay Kit
Bulletproof Triple
73732



Mega Jul Sport Belay Kit
Bulletproof Triple
73735

1 Checking the manufacturing codes

The manufacturing code is located on the outside of the closed carabiner spine.



If your carabiner is marked with a manufacturing code **2018 01** or **2018 02**, or if the manufacturing code is illegible, please perform the inspection as specified in section 2.



CHECK




Later batches (for example **2018 03** or **2019 01**) are not affected and can still be used.




OK

2 Checking the rivet

Please check that the rivet was fitted properly at the gate joint. On one side the rivet should have a head, on the other it should be pressed flat.



RETURN



OK

Please mail to:

EDELRID North America
736 SW Umatilla Ave. Suite H.
Redmond, OR 97756

Questions? Please read our Frequently Asked Questions (FAQs).